

[1] 安全に関する項目 ※はじめに必ずお読みください。
このたびはデジタル・マルチメータCD800a型をお買い上げいただき、誠にありがとうございます。
ご使用前に以下の取扱説明書をよくお読みいただき、正しく安全にご使用ください。そして常にご覧いただけるように製品と一緒にして大切に保管してください。

本文中の「△警告」の記載事項は、やけどや感電などの事故防止のため、必ずお守りください。

1-1 警告マークなどの記号説明
本器および「取扱説明書」に使用されている記号と意味について

△：警告です。やけどや感電などの人身事故を防止するためのものであります。

注記文は本器を壊すおそれのあるお取扱いや測定についての注意文です。

±：グランド △：ダイオード ↗：ヒューズ

●：ブザー ■：コンデンサ ○：抵抗

□：直流(DC) Hz：周波数 %：デューティー比

～：交流(AC) □：二重絶縁または強化絶縁

+: プラス └：テストリード(赤) ─：マイナス └：テストリード(黒)

1-2 安全使用のための警告文

△ 警 告

以下の項目は、やけどや感電などの人身事故を防止するためのものであります。本器をご使用する際には必ずお守りください。

1. 3kVAを超える電力ラインでは使用しないこと。

2. AC30Vrms(42.4peak)またはDC60V以上の電圧は人体に危険なため注意すること。

3. 最大定格入力値(13参考)を超える信号は入力しないこと。

4. 最大過負荷入力値を超えるおそれがあるため、誘起電圧、サー

ジ電圧の発生する(モータ等)ラインの測定はしないこと。

5. 本体または、テストリードが傷んでいたり、壊れている場合は使用しないこと。

6. ケースまたは電池ふたを外した状態では使用しないこと。

7. ヒューズは必ず指定定格および仕様のものを使用すること。

ヒューズの代用品を用いたり、ヒューズ端子間を銅線で短絡したりするとは絶対にしないこと。


8. 測定中はテストリードのつばよりテスビン側を持たないこと。

9. テストリードは最初に接地側(テストリードの黒)を接続し、は

なす場合は最後に接地側をはすこと。

— 1 —

【3】各部の名称



— 3 —

5-3 抵抗(Ω)測定 最大測定抵抗 40MΩ

△ 警 告

入力端子には外部よりの電圧を絶対に加えないこと。

1) 測定対象 抵抗器や回路の抵抗を測ります。

2) 測定レンジ 400Ω～40MΩまでの6レンジ

3) 測定方法

①ファンクションスイッチをΩ/▶/◀/±に設定します。
②被測定物に赤、黒のテストビンをそれぞれ接続します。
③表示器の表示値を読み取ります。

④測定後は被測定物から赤、黒のテストビンをはなします。

備考：測定際に際ノイズの影響を受ける場合は、被測定物をCOM電位でシールドしてください。また、テストビンに指を触れて測定すると、人体の抵抗の影響を受け誤差を生じます。入力端子間の開放電圧は約0.4Vです。

●電圧の加わっている部分の抵抗測定はできません。

— 4 —

5-4 ダイオード(▶)テスト

△ 警 告

測定端子には外部よりの電圧を絶対に加えないこと。

1) 使用対象 ダイオードの良否をテストします。

2) 使用方法

①ファンクションスイッチをΩ/▶/◀/±に合わせます。
②SELECTスイッチで▶を選択します。

③ダイオードのカソード側に黒のテストビンを、アノード側に赤のテストビンを接続します。

④表示器にダイオードの順方向電圧降下が表示されます。

— 7 —

●直流電流(DCmA)最大定格入力電流DC400mA

●交流電流(ACmA)最大定格入力電流AC400mA

1) 測定対象

DCA：直流回路の電流を測ります。

ACA：交流回路の電流を測ります。

2) 測定レンジ

DC/AC400mA, 400mAの2レンジ

3) 測定方法

①ファンクションスイッチをmAに設定しSELECTスイッチでDCまたはACを選択します。

②被測定回路に赤、黒のテストビンを負荷と並列になるように接続します。

●DCmA：被測定回路のマイナス電位側に黒のテストビンを、プラス電位側のテストビンを並列に接続します。

●ACmA：被測定回路と並列に赤、黒のテストビンをそれぞれ接続します。

③表示器の表示値を読み取ります。

④測定後は被測定回路から赤、黒のテストビンをはなします。

◆mAファンクションにてHz%の設定になりますが、Hz%ファンクションで動作ください。

— 8 —

【6】保守管理について

△ 警 告

1. この項目は安全上重要なです。本説明書をよく理解して管理を行なうこと。

2. 安全と確度の維持のために1年に1回以上は校正、点検を実施すること。

6-1 保守点検

1) 外観

●落とすなどにより、外観が壊れていませんか？

2) テストリード

●テストリードのコード部分が傷んでいませんか？

●テストリードのどこかの箇所から芯線が露出しているかもしれませんか？

備考：以上の項目に該当するものはそのまま使用せず、修理または

新しいものと交換してください。また、テストリードが切れたりしていないことを【5】-1を参照して確認してください。

— 11 —

10. 測定中は他のファンクションまたは他のレンジに切り換えないこと。

11. 測定ごとのレンジおよびファンクション確認を確實に行なうこと。
12. 本器または手が水等でぬれた状態での使用はしないこと。
13. テストリードは指定タイプのものを使用すること。
14. 電池交換およびヒューズ交換を除く修理・改造は行わないこと。
15. 年1回以上の点検は必ず行なうこと。
16. 屋内で使用すること。

10. 測定中は他のファンクションまたは他のレンジに切り換えないこと。
11. 測定ごとのレンジおよびファンクション確認を確實に行なうこと。
12. 本器または手が水等でぬれた状態での使用はしないこと。
13. テストリードは指定タイプのものを使用すること。
14. 電池交換およびヒューズ交換を除く修理・改造は行わないこと。
15. 年1回以上の点検は必ず行なうこと。
16. 屋内で使用すること。

1-3 最大過負荷保護入力値

ファンクション	入力端子	最大定格入力値	最大過負荷保護入力値
V	② (赤)	DC・AC600V	DC600V AC600V or Peak Max 840V
Ω/▶/◀/±	△電圧・電流 入力禁止		
Hz/%	② (黒)	DC・AC600V	
mA		DC・AC400mA	0.5A/250V Fuse

*交流電圧は正弦波交流の実効値での値。

【2】用途と特長

2-1 用 途 本器は弱電回路の測定用に設計された、携帯用デジタル・マルチメータです。小型通信機器や家電製品、電灯線電圧や各種電池などの測定はもちろん、付加機能を使って回路分析などに威力を發揮します。

2-2 特 長

●IEC61010-1に準拠した安全設計。
●文字高17.5mmのハッキリと見やすいLCD採用。
●Hz/%測定機能付。
●静電容量測定機能付。
●ボディーカバーは本体の保護やスタンドにもなり、内側には角チップ固定抵抗器の測定を補助する設計がなされています。

— 2 —

sanwa


MM

CD800a DIGITAL MULTIMETER 取扱説明書

CE

sanwa®

保証書



保証規定

sanwa



CD800a DIGITAL MULTIMETER

INSTRUCTION MANUAL

SANWA ELECTRIC
INSTRUMENT CO., LTD.
Dempa Bldg., Sotokanda 2-Chome
Chiyoda-Ku, Tokyo, Japan



[4] DESCRIPTION OF FUNCTIONS

⚠ WARNING

In the case of action or cancel that function as follows, do not turn the function switch in the condition applied input.

4-1 Function Switch

Turn this switch to turn on and off the power and to select the functions of V \sim , Ω / μ A / Hz / %, mA \sim

4-2 SELECT : Measurement Function Select

When the SELECT button is pressed (\rightarrow), the functions change as follows.

- In the case of V, mA, the modes change as: $\sim \rightarrow \sim \rightarrow \sim$.
- In the case of Ω , μ A, Hz , the modes change: $\Omega \rightarrow \mu\text{A} \rightarrow \text{Hz} \rightarrow \Omega$

4-3 RANGE : Range Hold

Press the RANGE button momentary to set the manual range mode, then 'AUTO' disappears in the display. In manual range mode, press the button again to step through the ranges. To return to the auto mode, press the button for 1 sec. or more, then 'AUTO' is shown.

*Manual mode is not available in Hz , Hz duty measurement, diode check, cont. buzz functions.

4-4 ΔREL : Relative Mode

Relative zero allows the user to offset the meter consecutive measurements with the displaying reading as the reference value. Press the ΔREL button momentarily to activate and to exit relative zero mode.

4-5 HOLD : Data Hold

When the HOLD button is pressed, the display is hold ('DH' is shown on the display). The display will not be changed while the function is active. Press the button again to cancel the function ('DH' on the display disappears.)

*DATA HOLD function does not work when measuring frequency.

4-6 Hz% : Frequency and duty cycle select button

Frequency and duty cycle measurement functions are activated alternatively by pressing the button. In the case of the mode change as Hz \rightarrow %

4-7 Auto Power Off

The meter will enter a low power consumption sleep mode automatically to extend battery life after approximately 30 minutes of no function switch or push button operations. To wake up the meter from Auto Power Off, press any buttons momentarily or turn the function switch to the OFF position. Then turn back on again. To disable the Auto Power Off feature, press the SELECT button while turning the function switch on.

*Always turn the function switch to the OFF position when the meter is not in use.


— 4 —

(3) Apply the black test pins to the cathode of the diode and the red test pin to the anode.
(4) Make sure that the display shows a diode forward voltage drop.

(5) Replace the red and black test pins, make sure that the display is '0.0V' reading.

(6) After measurement, release the red and black test pins from the object measured.

*The input terminals open voltage is about 1.5V



5-5 Checking Continuity (•))

⚠ WARNING

Never apply voltage to the input terminals.

1) Applications

Checking the continuity of wiring and selecting wires.

2) How to use


- ① Set the FUNTION switch at Ω / μ A / Hz / %.
- ② Select \bullet) by pressing the SELECT button.

③ Apply the red and black test pins to a circuit or conductor to measure.

④ The continuity can be judged by whether the buzzer sounds or not.

⑤ After measurement, release the red and black test pins from the object measured.

● Threshold: 10~70 Ω



— 8 —

6-2 Calibration

The manufacturer may conduct the calibration and inspection. For more information, please contact the dealers.

6-3 Battery and Fuse Replacement

⚠ WARNING

1. If the rear case or the battery lid is removed with input applied to the input terminals, you may get electrical shock. Before starting the work, always make sure that no input is applied.

2. Before starting the work, be sure to turn OFF the main unit power and release the test leads from the circuit.

3. Be sure to use a fuse of the specified rating or type. Never use a substitute of the fuse or never make a short circuit of the fuse.


① Remove the battery lid screw with a screwdriver.

② Take out the battery or fuse and replace it with a new one.

③ Attach the battery lid and fix with the screw.

⚠ CAUTION

Set battery with its polarities facing in the correct directions.



6-4 Storage

⚠ CAUTION

1. The panel and the case are not resistant to volatile solvent and must not be cleaned with thinner or alcohol.

2. Cleaning, use dry, soft cloth and wipe it lightly.

3. The panel and the case are not resistant to heat. Do not place the instrument near heat-generating devices (such as a soldering iron).

3. Do not store the instrument, in a place where it may be subjected to vibration or from where it may fall.

4. For storing the instrument, avoid hot, cold or humid places or places under direct sunlight or where condensation is anticipated.

— 12 —

[1] SAFETY PRECAUTIONS Before use, read the following safety precautions.
This instruction manual explains how to use your new digital multimeter CD800a safely. Before use, please read this manual thoroughly. After reading it, keep it together with the product for reference to it when necessary. The instruction given under the heading of '⚠ WARNING' must be followed to prevent accidental burn or electrical shock.

1-1 Explanation of Warning Symbols

The meaning of the symbols used in this manual and attached to the product is as follows.

⚠ Very important instruction for safe use.

The warning messages are intended to prevent accidents to operating personnel such as burn and electrical shock.

The caution messages are intended to prevent damage to the instrument.

\ominus : Ground	\blacktriangleright : Diode	\ominus : Fuse
\bullet : Buzzer	\parallel : Capacitance	Ω : Resistance
DC : Direct current(DC)	Hz : Frequency	
$\%$: Duty cycle	\sim : Alternating current(AC)	
\square : Double insulation(Protection Class II)		
$+$: Plus input	\ominus (Red)	$-$: Minus input \ominus (Black)

1-2 Warning Instruction for Safe Use

The warning messages are intended to prevent accidents to operating personnel such as burn and electrical shock.

The caution messages are intended to prevent damage to the instrument.

\ominus : Ground	\blacktriangleright : Diode	\ominus : Fuse
\bullet : Buzzer	\parallel : Capacitance	Ω : Resistance
DC : Direct current(DC)	Hz : Frequency	
$\%$: Duty cycle	\sim : Alternating current(AC)	
\square : Double insulation(Protection Class II)		
$+$: Plus input	\ominus (Red)	$-$: Minus input \ominus (Black)

⚠ WARNING

To ensure the meter is used safely, be sure to observe the instruction when using the instrument.

1.Never use meter on the electric circuits that Exceed 3kVA.

2.Never apply an input signal exceeding the maximum rating input value.

3.Never use meter if the meter or test leads are damaged or broken.

4.Pay special attention when measuring the voltage of AC 30Vrms(42.4V peak) or more to avoid injury.

5.Never use meter for measuring the line connected with equipment (i.e.motors) that generates induced or surge voltage since it may exceed the maximum allowable voltage.

6.Never use uncased meter.

7.Be sure to use a fuse of the specified rating or type. Never use a substitute of the fuse or never make a short circuit of the fuse.

8.When connecting and disconnecting the test leads, first connecting the ground lead(black one). When disconnecting them, the ground lead must be disconnected last.

9.Always keep your fingers behind the finger guards on the probe when making measurements.

— 1 —


[5] MEASUREMENT PROCEDURE

5-1 Start-Up Inspection

⚠ WARNING

1. Make sure that no low battery indication appear in the display.
2. Never use meter if the meter or test leads are damaged or broken.
3. Check continuity of test leads & fuse.

※ No display may suggest that a battery be exhausted.



5-2 Voltage measurement

⚠ WARNING

1. Never apply an input signal exceeding the maximum rating input value.
2. Be sure to disconnect the test pins from the circuit when changing the function.
3. Always keep your fingers behind the finger guards on the probe when making measurements.

— 5 —

5-6 Capacitance Measurement (||)

⚠ WARNING

Never apply voltage to the input terminals.

⚠ CAUTION


1. Discharge the capacitance before measurement.
2. This is not suitable for measurement of electrolytic condenser such as a large leakage condenser.
3. It takes a while to measure large capacitance.

- 1) Applications Measures capacitance of low leakage condenser such as film condenser.
- 2) Measuring ranges 5 ranges from 5.0nF to 100.0 μ F (Auto range).
- 3) Measurement procedure ① Set the FUNTION switch at Ω / μ A / Hz / % and select \square with the SELECT button.

- ② Select \parallel by pressing the SELECT button.
- ③ Press the REL button for zero setting (0.00nF).
- ④ Apply the red and black test pins to a conductor to measure.
- ⑤ Read the value on the display.
- ⑥ After measurement, release the red and black test pins from the object measured.

*Manual range is not available in capacitance measurement.

*Readings are unstable because of stray capacitance in test leads or noise.



5-7 Hz / % Measurements (Hz / %)

⚠ WARNING

Never apply an input signal exceeding the maximum rating input value.

— 9 —

[7] AFTER-SALE SERVICE

7-1 Repair

If the multimeter fails during use, check the following items before sending it for repair.

- Is the battery not exhausted?
- Is the fuse not blown?

We repair defective product at cost. When mailing it to us for repair, do not use the same cardboard box in which it was delivered to you because it may receive damage in transit. Please send it in a box at least five times as large as the original box with enough cushioning material stuffed around it.

7-2 For Information or Enquiries

If you need information regarding purchase of repair parts or if you have any other Sales related questions, please contact the dealer, selling agent, or maker.

7-3 Sanwa Web Site

http://www.sanwa-meter.co.jp E-mail:exp_sales@sanwa-meter.co.jp

[8] SPECIFICATIONS

8-1 General Specification

Measuring	Δ method

<tbl_r cells="2" ix="2" maxcspan="1" maxr