



# Standard Test Methods for Vulcanized Fibre Used for Electrical Insulation<sup>1</sup>

This standard is issued under the fixed designation D 619; the number immediately following the designation indicates the year of original adoption or, in the case of revision, the year of last revision. A number in parentheses indicates the year of last reapproval. A superscript epsilon (ε) indicates an editorial change since the last revision or reapproval.

## 1. Scope

1.1 These test methods cover the procedures for testing vulcanized fibre sheets, tubes, and rods of such grades as can be used for electrical insulation.

1.2 The procedures appear in the following sections:

Procedure	Section
Arc resistance	23
Ash	6
Bond strength (ply adhesion)	16
Bursting strength	14
Compressive strength	12, 25, 30
Conditioning	4
Density	17, 26, 32
Dielectric strength	18, 27
Dimensional measurements	28, 33
Flammability	22
Flexural strength	13, 31
Silica	7
Tearing strength	11
Tensile strength	10, 24, 29
Thickness (sheets)	20
Resistance to impact	15
Rockwell hardness	19
Volatile matter	8
Water absorption	5
Zinc chloride	9

1.3 The values stated in inch-pound units are to be regarded as the standard. The SI values given in parentheses are for information only.

1.4 *This standard does not purport to address all of the safety concerns, if any, associated with its use. It is the responsibility of the user of this standard to establish appropriate safety and health practices and determine the applicability of regulatory limitations prior to use.* Specific hazard statements are given in 7.3 and 22.1.

NOTE 1—The test methods described herein are similar technically to those described in IEC Publication 60667-2. Not all of the tests in this document are included in IEC 60667-2, and the procedures in the two publications are not completely identical; but it is expected that comparable results will be obtained from most of the procedures and comparative tests should be made if necessary before directly comparing results of tests using the different procedures.

## 2. Referenced Documents

### 2.1 ASTM Standards:

- D 149 Test Method for Dielectric Breakdown Voltage and Dielectric Strength of Solid Electrical Insulating Materials at Commercial Power Frequencies<sup>2</sup>
- D 202 Test Methods for Sampling and Testing Untreated Paper Used for Electrical Insulation<sup>2</sup>
- D 229 Test Methods for Rigid Sheet and Plate Materials Used for Electrical Insulation<sup>2</sup>
- D 256 Test Methods for Determining the IZOD Pendulum Impact Resistance of Plastics<sup>3</sup>
- D 348 Test Methods for Rigid Tubes Used for Electrical Insulation<sup>2</sup>
- D 349 Test Methods for Laminated Round Rods Used for Electrical Insulation<sup>2</sup>
- D 374 Test Methods for Thickness of Solid Electrical Insulation<sup>2</sup>
- D 495 Test Method for High-Voltage, Low-Current, Dry Arc Resistance of Solid Electrical Insulation<sup>2</sup>
- D 570 Test Method for Water Absorption of Plastics<sup>3</sup>
- D 668 Test Methods of Measuring Dimensions of Rigid Rods and Tubes Used for Electrical Insulation<sup>2</sup>
- D 689 Test Method for Internal-Tearing Resistance of Paper<sup>4</sup>
- D 695 Test Method for Compressive Properties of Rigid Plastics<sup>3</sup>
- D 785 Test Method for Rockwell Hardness of Plastics and Electrical Insulating Materials<sup>3</sup>
- D 792 Test Methods for Density and Specific Gravity (Relative Density) of Plastics by Displacement<sup>3</sup>
- D 828 Test Method for Tensile Properties of Paper and Paperboard Using Constant-Rate-of-Elongation Apparatus<sup>4</sup>
- D 952 Test Method for Bond or Cohesive Strength of Sheet Plastics and Electrical Insulating Materials<sup>3</sup>
- D 1711 Terminology Relating to Electrical Insulation<sup>2</sup>
- D 6054 Practice for Conditioning Electrical Insulating Materials for Testing<sup>5</sup>

<sup>1</sup> These test methods are under the jurisdiction of ASTM Committee D-9 on Electrical and Electronic Insulating Materials and are the direct responsibility of Subcommittee D09.07 on Flexible and Rigid Insulating Materials

Current edition approved Oct. 10, 1999. Published November 1999. Originally published as D 619 – 41. Last previous edition D 619 – 94.

<sup>2</sup> *Annual Book of ASTM Standards*, Vol 10.01.

<sup>3</sup> *Annual Book of ASTM Standards*, Vol 08.01.

<sup>4</sup> *Annual Book of ASTM Standards*, Vol 15.09.

<sup>5</sup> *Annual Book of ASTM Standards*, Vol 10.02.



## 2.2 IEC Standard:

IEC 60667-2 Specification for Vulcanized Fibre for Electrical Purposes—Part 2: Methods of Test<sup>6</sup>

## 3. Terminology

### 3.1 Definitions:

3.1.1 *vulcanized fibre, n*—a material made from chemically gelatinized cellulosic paper or board using zinc chloride as the gelatinizing agent.

3.1.1.1 *Discussion*—The zinc chloride is subsequently removed by leaching. The resulting product, after being dried and finished by calendering, is a material of partially regenerated cellulose in which the fibrous structure is retained in varying degrees depending on the grade of paper used and on the processing conditions. Material up to about 25 mm in thickness is produced by bonding multiple layers of paper (or board) after chemical treatment. Vulcanized fibre does not contain vulcanized rubber or sulfur as the name might imply. Thin vulcanized fibre has sometimes been termed “fish paper”.

3.1.2 For definitions of other terms used in this standard refer to Terminology D 1711.

3.2 *Definitions of Terms Specific to This Standard:* In referring to the cutting of specimens and the application of the load, the following definitions of terms apply:

3.2.1 *crosswise (CW)*—the direction of the sheet which is at 90° to the lengthwise direction, and which is normally the weakest direction in flexure. For some materials, including the raw materials used for manufacture of materials considered herein, this direction may be designated as the cross-machine direction or the weft direction.

3.2.2 *edgewise loading*—mechanical force applied in the plane of the original sheet or plate.

3.2.3 *flatwise loading*—mechanical force applied normal to the surfaces of the original sheet or plate.

3.2.4 *lengthwise (LW)*—the direction of the sheet which is strongest in flexure.

3.2.4.1 *Discussion*—For some materials, including the raw materials used for the manufacture of materials considered herein, this direction may be designated as the machine direction or the warp direction.

3.3 In the case of thin material, the following definitions of terms apply:

3.3.1 *machine direction*—the lengthwise direction in which the paper is formed and travels on the paper machine, wire, or cylinder.

3.3.2 *cross direction*—the direction at right angles to the machine direction.

NOTE 2—These definitions of terms conform to the practice of the paper industry.

## 4. Conditioning

4.1 Vulcanized fibre shall be conditioned for mechanical tests in accordance with Practice D 6054, using Procedure A for conditioning material 0.045 in. (1.14 mm) and under in thickness, and Procedure B for conditioning material over

0.045 in. in thickness. In case of dispute in tests of materials over 0.045 in. in thickness, the material shall be exposed for 48 h at standard laboratory atmosphere prior to conditioning by Procedure B.

4.2 Vulcanized fibre shall be conditioned for electrical tests in accordance with Practice D 6054, using Procedure A. In case of dispute, a referee test shall be used in which the time of exposure to standard laboratory atmosphere is increased to a minimum period of 7 days for all thicknesses.

NOTE 3—Conditioning of specimens may be undertaken (1) for the purpose of bringing the material into equilibrium with normal or average room conditions of 23°C and 50 % relative humidity, (2) simply to obtain reproducible results regardless of the previous history of exposure, or (3) to subject the material to various conditions of temperature or humidity in order to predict its service behavior.

The conditioning of Procedure B prescribed in Practice D 6054 to obtain reproducible results may give physical values somewhat higher or somewhat lower than the values at equilibrium under normal conditions, depending upon the test. This procedure for conditioning is used because of the relatively short time required. To bring the material to an equilibrium condition in a controlled humidity would require a long period of time which might extend over many months, for example, for thicknesses over 25 mm. The exact length of time would depend upon such factors as thickness, grade, and previous history of the specimens, and it would be too long for ordinary commercial test purposes. It is probable that the time of exposure for some very thin sizes of material conditioned in accordance with Procedure A may be reduced, but sufficient data on the various thicknesses are not yet available to permit a decision to be made.

## METHODS APPLICABLE TO SHEETS, TUBES, AND RODS

### 5. Water Absorption

5.1 *Significance and Use*—This test method is a guide for the proportion of water absorbed in vulcanized fibre sheets, tubes, and rods and to the effects thereof on certain electrical and mechanical properties. It also is useful in determining the uniformity of quality in these materials.

5.2 *Procedure*—Determine water absorption in accordance with Test Method D 570 on specimens dried in an oven for 1 h at 105 to 110°C prior to immersion in water.

### 6. Ash

6.1 *Significance and Use*—This test method provides a procedure for determining the amount of ash of a dried specimen which may be useful in determining the continuity of quality.

6.2 *Test Specimen*—The test specimen shall consist of 2 to 5 g of vulcanized fibre in the form of finely divided particles, such as millings or filings.

6.3 *Procedure*—Dry the test specimen for 2 h at 105 to 110°C and weigh. Then ignite the specimen to constant weight in a crucible and reweigh. Calculate the percentage of ash, based on the weight of the dried specimen.

6.4 *Report*—Report the following information:

6.4.1 Identification of the material, and

6.4.2 The percentage by weight of ash.

6.5 *Precision and Bias:*

<sup>6</sup> Available from American National Standards Institute, 11 W. 42nd St., 13th Floor, New York, NY 10036.

6.5.1 This test method has been used for many years, but no information has been presented to ASTM upon which to base a precision statement. No activity has been planned to develop such information.

6.5.2 This test method has no bias because the value for percentage of ash is determined solely in terms of this test method itself.

## 7. Silica

7.1 *Significance and Use*—This test method is useful in determining the continuity of quality of vulcanized fibre sheets, tubes, and rods and in providing a means of evaluating changes in the leaching medium and the efficiency of the leaching process.

7.2 *Test Specimen*—The test specimen shall consist of approximately 3 g of vulcanized fibre in the form of finely divided particles, such as millings or filings.

7.3 *Procedure*—(**Warning**—Both hydrochloric acid (HCl) and hydrofluoric acid (HF) are corrosive and toxic. Take care to avoid spillage and contact with the skin. Evaporate solutions of these acids in a well-ventilated fume hood.) Dry the test specimen for 1 h at 105 to 110°C. Transfer the dried specimen to a crucible and slowly ignite it to constant weight. Wet the ash with distilled water and transfer to a heat-resistant glass beaker. Add about 75 mL of HCl (sp gr 1.19) and cover the beaker with a watchglass. Evaporate the contents of the beaker to dryness. To the residue slowly add 10 mL of HCl (sp gr 1.19) followed by 75 mL of distilled water. Filter the mixture through ashless filter paper and wash with cold water, then with warm water, until the filtrate is free of chlorides. Ignite the filter paper to constant weight in a weighed platinum crucible. Then add 4 mL of HF (48 to 60 %) and apply heat until all white fumes are driven off. Cool and weigh the crucible. The difference between this weight and the previous one indicates silicon present as silica. The results shall be expressed as a percentage of the weight of the dried specimen.

7.4 *Report*—Report the following information:

7.4.1 Identification of the material, and

7.4.2 The percentage by weight of silica.

7.5 *Precision and Bias*:

7.5.1 This test method has been used for many years, but no information has been presented to ASTM upon which to base a precision statement. No activity has been planned to develop such information.

7.5.2 This test method has no bias because the value for percentage of silica is determined solely in terms of this test method itself.

## 8. Volatile Matter

8.1 *Significance and Use*—The presence of high levels of volatile matter may be detrimental to the use of vulcanized fibre sheets, tubes, and rods in some electrical applications. Data on volatile content may determine the suitability for a particular application and may be useful in determining the continuity of quality.

8.2 *Purpose*—This test method is intended for the rapid determination of the amount of moisture and other volatile matter in vulcanized fibre of all grades and thicknesses.

8.3 *Test Specimens*—Prepare the test specimen which consists of the minimum number of pieces of fibre required to give a total weight of at least 1 g, as follows:

8.3.1 *Sheets*—For sheets less than  $\frac{1}{16}$  in. (1.59 mm) in thickness, the pieces for the test specimen shall be 75 by 25 mm by the thickness of the sheet; for sheets  $\frac{1}{16}$  in. and over in thickness, the pieces for the test specimen shall be 75 by 3 mm by the thickness of the sheet. The pieces shall be band-sawed or sheared from the sample so as to produce smooth edges free of cracks. The sawed faces shall be sanded or filed to remove any protruding sections that might be broken off during the test. The sample shall be sawed slowly so that the fibre is not heated appreciably. The thickness of the specimens shall be measured to the nearest 0.001 in. (0.025 mm) in the direction perpendicular to the natural faces of the original sample.

8.3.2 *Tubes*—For tubes less than  $\frac{1}{16}$  in. (1.59 mm) in wall thickness, the pieces for the test specimen shall be 25-mm lengths. For tubes  $\frac{1}{16}$  in. and over in wall thickness, the pieces for the test specimen shall be 3-mm lengths slowly cut with a band saw.

8.3.3 *Rods*—For rods less than  $\frac{3}{16}$  in. (4.76 mm) in diameter, the pieces for the test specimen shall consist of continuous lengths. For rods  $\frac{3}{16}$  in. and over in diameter, the pieces for the test specimen shall be 3-mm lengths slowly cut with a band saw.

8.4 *Procedure*—Test three specimens, each consisting of one or more pieces of fibre as required, individually. Weigh each specimen to the nearest 1 mg, and place it in a mechanical convection oven maintained at a temperature of  $135 \pm 2^\circ\text{C}$  and heated for the period prescribed in the following table. Specimens less than  $\frac{1}{32}$  in. (0.80 mm) in thickness shall be weighed (but not heated) in a weighing bottle.

	Size	Heating Period, h
Sheets	Under $\frac{1}{16}$ in. (1.59 mm), in thickness	2
	$\frac{1}{16}$ and over in thickness	4
Tubes	Under $\frac{1}{16}$ in. in wall thickness	2
	$\frac{1}{16}$ in. and over in wall thickness	4
Rods	Under $\frac{3}{16}$ in. (4.76 mm) in diameter	2
	$\frac{3}{16}$ in. and over in diameter	4

8.4.1 Remove the specimens from the oven, cool in a desiccator, and weigh to the nearest 1 mg. The difference between the original weight and the final weight of the specimens shall be considered as the volatile matter content.

8.5 *Calculation*—Calculate the percentage of volatile matter content of the specimen as follows:

$$\text{Volatile matter, \%} = [(W_1 - W_2)/W_2] \times 100 \quad (1)$$

where:

$W_1$  = original weight of specimen, and

$W_2$  = final weight of specimen.

8.6 *Report*—Report the following information:

8.6.1 Color and dimensions of the specimen, and

8.6.2 Percentage of volatile matter.

8.7 *Precision and Bias*:

8.7.1 This test method has been used for many years, but no information has been presented to ASTM upon which to base a precision statement. No activity has been planned to develop such information.



8.7.2 This test method has no bias because the value for percentage of volatile matter is determined solely in terms of this test method itself.

## 9. Zinc Chloride

9.1 *Significance and Use*—The amount of zinc chloride is indicative of the efficiency of the leaching process used in the manufacture of vulcanized fibre sheets, tubes, and rods.

9.2 *Test Specimen*—The test specimen shall consist of approximately 3 g of vulcanized fibre in the form of finely divided particles, such as millings or filings.

9.3 *Procedure*—Dry the test specimen for 1 h at 105 to 110°C. Place the dried specimen in a Soxhlet, Wiley-Richardson, or similar type of extractor and extract with distilled water for 3 h. The rate of extraction with the Wiley-Richardson size of extractor shall be sufficient to cause the tube containing the specimen to be filled by condensation and emptied by the siphon at least six times per hour. When the Soxhlet or similar size extractor is used, the tube shall be filled and emptied at a rate of at least three cycles per hour. After this extract has cooled, add 0.5 mL of  $K_2CrO_4$  solution (10 %) and titrate the extract with standard  $AgNO_3$  solution. The end point is indicated by the appearance of a permanent red color. Make a blank test on an equal volume of distilled water and  $K_2CrO_4$  solution and subtract the result from that of the specimen. Calculate the net result expressed as  $ZnCl_2$ .

9.4 *Report*—Report the following information:

9.4.1 Identification of the material, and

9.4.2 Percentage by weight of  $ZnCl_2$ .

9.5 *Precision and Bias*:

9.5.1 This test method has been used for many years, but no information has been presented to ASTM upon which to base a precision statement. No activity has been planned to develop such information.

9.5.2 This test method has no bias because the value for percentage of zinc chloride is determined solely in terms of this test method itself.

## METHODS APPLICABLE TO SHEETS

NOTE 4—In addition to the test methods for sheets covered in the following Sections 10-23, inclusive, the methods described in Sections 5-9 are also applicable to sheet materials.

## 10. Tensile Strength

10.1 *Significance and Use*—Tensile strength is of importance as a measurement of uniformity and quality of the material. It also serves to indicate its ability to withstand stress in application and service.

10.2 For sheets 0.030 in. (0.762 mm) and under in thickness, determine the tensile strength in accordance with the procedure described in Test Method D 828.

10.3 For sheets over 0.030 in. (0.762 mm) in thickness, determine the tensile strength in accordance with the procedure described in Test Methods D 229.

## 11. Tearing Strength

11.1 *Significance and Use*—Resistance to tearing is an important property for measuring suitability for certain application processes and as a means of determining the continuity of quality.

11.2 Determine the tearing strength of sheets 0.030 in. (0.762 mm) and under in thickness in accordance with the procedure described in Test Method D 689.

## 12. Compressive Strength

12.1 *Significance and Use*—Compressive test data provide information useful in research and development, engineering design, determining the suitability of the material for specific load requirements in service, and in determining the continuity of quality.

12.2 Determine the compressive strength on four specimens using the procedure described in Test Method D 695.

## 13. Flexural Strength

13.1 *Significance and Use*—Flexural strength data are useful for determining the continuity of quality and may provide important guidance in the design and construction of electrical equipment.

13.2 Determine the flexural strength of sheets  $\frac{1}{16}$  in. (1.59 mm) and over in thickness in accordance with the procedure described in Test Methods D 229.

## 14. Bursting Strength

14.1 *Significance and Use*—Bursting strength data are useful as a means of determining the continuity of quality and as an index of resistance to puncture under stresses found in construction and assembly of electrical equipment.

14.2 Determine the bursting strength of sheets 0.060 in. (1.52 mm) and under in thickness in accordance with the procedure described in Test Methods D 202.

## 15. Resistance to Impact

15.1 *Significance and Use*—Data on impact resistance are useful in evaluating the suitability of vulcanized fibre sheets in applications where shock stresses are present in the construction, assembly, or service use of equipment in which it is used. It also serves as a guide for determining the continuity of quality.

15.2 Determine the impact strength in accordance with Test Methods D 256.

## 16. Bond Strength (Ply Adhesion)

16.1 *Significance and Use*—Bond strength data are useful in evaluating the efficiency of the calendering operation and the suitability of vulcanized fibre sheets for applications where the plies are subjected to stresses that may cause delamination. They are also useful in determining the continuity of quality.

16.2 Determine the bond strength (ply adhesion) in accordance with Test Method D 952.

## 17. Density

17.1 *Significance and Use*—Density data are useful in determining the economics of applications in electrical equipment, as well as a means of evaluating the continuity of quality.

17.2 For sheets 0.020 in. (0.51 mm) and under in thickness, weigh a conditioned specimen of suitable size to the nearest 1 mg. Measure the thickness and area of the specimen, and calculate the apparent density as follows:



$$\text{Apparent density, g/cm}^3 = (W/V) \times 0.061 \quad (2)$$

where:

$W$  = weight, g, and

$V$  = volume, in.<sup>3</sup>

17.3 For sheets over 0.020 in. in thickness, use the procedure described in Test Methods D 792.

17.4 *Report*—Report the following information:

17.4.1 Identification of the material, and

17.4.2 Apparent density in g/cm<sup>3</sup>.

17.5 *Precision and Bias*:

17.5.1 This test method has been used for many years, but no information has been presented to ASTM upon which to base a precision statement. No activity has been planned to develop such information.

17.5.2 This test method has no bias because the value for percentage of apparent density is determined solely in terms of this test method itself.

## 18. Dielectric Strength

18.1 *Significance and Use*—This test method provides a basis for determining the continuity of quality as well as an index of the effect of conditioning and selected mechanical stresses to which the material may be subjected in construction and service.

18.2 Determine the dielectric strength in accordance with Test Method D 149, with the exceptions described in the procedure for dielectric strength in Test Methods D 229.

## 19. Rockwell Hardness

19.1 *Significance and Use*—This test method provides data useful as a control test for evaluating the punching quality and, to a limited extent, the efficiency of the chemical treatment and calendaring operation in the manufacture of vulcanized fibre sheets. It also may be useful in grading this material as to its resistance to indentation during assembly or construction of electrical equipment of which it is a component.

19.2 Determine the Rockwell hardness in accordance with Test Method D 785, except as follows:

19.2.1 Prior to measurement of Rockwell hardness by either Method A or B of Test Method D 785, materials shall be conditioned in accordance with Section 4 of this test method, and

19.2.2 For Method A, the R scale shall be used in all tests and the letter R shall precede all Rockwell hardness numbers.

19.2.3 This test is not recommended for sizes below 1/16 in. (1.6 mm) in thickness because of the difficulty in maintaining satisfactory contact between surfaces of the individual pieces in the pile-up.

## 20. Thickness

20.1 *Significance and Use*—Design of electrical equipment requires that the thickness of sheets be known. Also, since electrical properties such as dielectric strength, permittivity, and volume resistivity require that the thickness be measured in order to be computed, these data are necessary.

20.2 *On Test Specimens*—All thickness measurements of test specimens shall be made using a machinist's micrometer in the manner outlined under Method B of Test Methods D 374.

20.3 *On Large Sheets*—In the factory, thickness measurements of large sheets of material may be made by using a gage mounted on a yoke of sufficient size and rigidity to permit accurate measurements of the thickness at the center of the sheet.

## 21. Machine and Cross Directions

21.1 *Test Specimens*—For sheets less than 1/32 in. (0.79 mm) in thickness, prepare square specimens of about 50 mm in size, and for sheets 1/32 in. and greater in thickness prepare similar specimens of about 25 mm in size.

21.2 *Procedure*—Measure the specimen in two directions at right angles to each other, using a steel rule graduated in 1/64-in. (0.5-mm) divisions for the 50-mm square specimen, and using a micrometer caliper for the 25-mm square specimen. Immerse the specimens in water until swelling has occurred, remove, and remeasure them immediately at the same locations that were measured before. The dimension which is found to show the greatest percentage increase during the immersion shall be considered the cross-direction.

## 22. Flammability

22.1 *Warning*—This standard should be used to measure and describe the properties of materials, products, or assemblies in response to heat and flame under controlled laboratory conditions and should not be used to describe or appraise the fire hazard or fire risk of materials, products, or assemblies under actual fire conditions. However, results of this test may be used as elements of a fire risk assessment which takes into account all of the factors which are pertinent to an assessment of the fire hazard of a particular end use.

22.2 *Significance and Use*—This test method serves to evaluate comparatively and relatively the resistance to ignition and the extent of burning if ignition occurs when the material is exposed to a temperature sufficiently high, either by malfunction of the apparatus in which it is a component or by normal-use exposure to arcing, for example.

22.3 Determine the burning rate or flame resistance, or both, in accordance with Method I or II respectively of Test Methods D 229.

## 23. Arc Resistance

23.1 *Significance and Use*—This test method can be used to differentiate between materials with respect to their resistance to the action of a high-voltage, low-current arc in the proximity of their surfaces where relative ranking of materials is not the intended purpose. It may be useful in detecting changes in formulation and composition, and for the continuity of quality after correlation has been established with other types of simulated-service arc tests and with field experience.

23.2 Determine arc resistance in accordance with Test Method D 495.

## METHODS APPLICABLE TO TUBES

NOTE 5—In addition to the test methods for tubes covered in the following Sections 24-28, inclusive, the test methods described in Sections 5-9 are also applicable to tubes.



## 24. Tensile Strength

24.1 *Significance and Use*—Tensile strength is of importance as a measurement of uniformity and quality of the material. It also serves to indicate its ability to withstand stress in application and service.

24.2 Determine the tensile strength in accordance with the procedure described in Test Methods D 348.

## 25. Compressive Strength

25.1 *Significance and Use*—Compressive test data provide information useful in research and development, engineering design, determining the suitability of the material for specific load requirements in service, and in determining the continuity of quality.

25.2 Determine the compressive strength in accordance with the procedure described in Test Methods D 348.

## 26. Density

26.1 *Significance and Use*—Density data are useful in determining the economics of applications in electrical equipment, as well as a means of evaluating the continuity of quality.

26.2 Determine the density in accordance with the procedure described in Test Methods D 348.

## 27. Dielectric Strength

27.1 *Significance and Use*—This test method provides a basis for determining the continuity of quality as well as an index of the effect of conditioning and selected mechanical stresses to which the material may be subjected in construction and service.

27.2 Determine the dielectric strength in accordance with Test Method D 149, with the exceptions described in the procedure for dielectric strength in Test Methods D 348.

## 28. Dimensional Measurements

28.1 *Significance and Use*—This test method is used to measure dimensions in order to determine conformity with specification requirements for the material. It can also be used to determine the continuity of quality in manufacture and to evaluate the effects of various treatments on the physical and electrical properties of the material.

28.2 Determine the dimensional measurements of tubes in accordance with Test Methods D 668.

### METHODS APPLICABLE TO RODS

NOTE 6—In addition to the test methods for rods covered in Sections 29-32, inclusive, the test methods described in Sections 5-9 are also applicable to rods.

## 29. Tensile Strength

29.1 *Significance and Use*—Tensile strength is of importance as a measurement of uniformity and quality of the material. It also serves to indicate its ability to withstand stress in application and service.

29.2 Determine the tensile strength in accordance with the procedure described in Test Methods D 349.

## 30. Compressive Strength

30.1 *Significance and Use*—Compressive test data provide information useful in research and development, engineering design, determining the suitability of the material for specific load requirements in service, and in determining the continuity of quality.

30.2 Determine the compressive strength in accordance with the procedure described in Test Methods D 349.

## 31. Flexural Strength

31.1 *Significance and Use*—Flexural strength data are useful for determining the continuity of quality and may provide important guidance in the design and construction of electrical equipment.

31.2 Determine the flexural strength in accordance with the procedure described in Test Methods D 349.

## 32. Density

32.1 *Significance and Use*—Density data are useful in determining the economics of applications in electrical equipment, as well as a means of evaluating the continuity of quality.

32.2 Determine the density in accordance with the procedure described in Test Methods D 349.

## 33. Dimensional Measurements

33.1 *Significance and Use*—This test method is used to measure dimensions in order to determine conformity with specification requirements for the material. It can also be used to determine the continuity of quality in manufacture and to evaluate the effects of various treatments on the physical and electrical properties of the material.

33.2 Measure the dimensions of rods in accordance with Test Methods D 668.

## 34. Keywords

34.1 arc resistance; ash content; bond strength; bursting strength; compressive strength; density; dielectric strength; flame resistance; flexural strength; impact resistance; inside diameter; outside diameter; ply adhesion; rigid rods; rigid sheets; rigid tubes; Rockwell hardness; silica content; tear resistance (internal); tensile strength; thickness; volatile content; vulcanized fibre; wall thickness; water absorption; zinc chloride content



*ASTM International takes no position respecting the validity of any patent rights asserted in connection with any item mentioned in this standard. Users of this standard are expressly advised that determination of the validity of any such patent rights, and the risk of infringement of such rights, are entirely their own responsibility.*

*This standard is subject to revision at any time by the responsible technical committee and must be reviewed every five years and if not revised, either reapproved or withdrawn. Your comments are invited either for revision of this standard or for additional standards and should be addressed to ASTM International Headquarters. Your comments will receive careful consideration at a meeting of the responsible technical committee, which you may attend. If you feel that your comments have not received a fair hearing you should make your views known to the ASTM Committee on Standards, at the address shown below.*

*This standard is copyrighted by ASTM International, 100 Barr Harbor Drive, PO Box C700, West Conshohocken, PA 19428-2959, United States. Individual reprints (single or multiple copies) of this standard may be obtained by contacting ASTM at the above address or at 610-832-9585 (phone), 610-832-9555 (fax), or [service@astm.org](mailto:service@astm.org) (e-mail); or through the ASTM website ([www.astm.org](http://www.astm.org)).*