


## 载荷传感器选择表








### 载荷传感器


● 载荷传感器选择表







压缩载重测量用		额定容量																			登载页			
		N							kN							MN								
		5	10	50	100	200	300	500	1	2	5	10	20	30	50	100	200	500	1	2		5		
	型号名称																							
	小型、载重分布测量用																							
	LMA-A	●	●	●	●	●	●	●	●															2-13
小型压缩式	超小型 NEW LMB-A			●	●	●		●	●	●														2-14
	超小型 NEW LMBT-A			●	●	●		●	●	●														2-15
梁型	小型, 轻量 LUB-B			●	●	●	●	●	●	●	●	●												2-60
小型压缩式	端子式 LCX-A-ID							●	●	●	●	●												2-19
小型压缩式	不锈钢 LCN-A							●	●	●	●	●												2-17
压缩式	高温用 LC-FH							●	●	●	●	●			●	●	●							2-25
小型压缩式	直径21mm LMR-S-SA2									●	●	●	●											2-16
梁型	精度1/2000 LUB-C										●	●	●											2-61
压缩式 小型高容量	直径20, 25mm LCR-G-SA2											●	●	●	●									2-23
防爆型 压缩式	耐压防爆 2G4 LCS-D										●	●	●		●									2-29
薄型压缩式	全高25-50mm薄型 LCK-A										●	●	●		●	●	●							2-27
耐腐蚀型 压缩式	全不锈钢 LC-J										●	●	●		●	●	●							2-30
	精度1/2000 LC-V														●	●	●							2-21
高精度型	精度1/5000 LCH-F															●	●							2-28
	高容量, 精度1/1000 LCV-A																	●	●					2-18
一般用 压缩式	高容量 LC-E																			●	●			2-24





压缩载重测量用		额定容量												登载页										
		N		kN																				
		500	800	1	2	3	5	10	20	30	50	100	200		300									
不锈钢	食品容器・料斗用 LCTS-B 																							2-31
薄型	容器・料斗用 LCTA-A 																							2-33
	容器・料斗用 LCTB-A 																							2-35
	容器・料斗用 LCTE-A 																							2-37
	容器・料斗用 LCTD-A 																							2-39

拉伸载重测量用		额定容量																登载页						
		mN				N								kN										
		50	100	200	500	1	2	5	10	20	50	100	200	500	1	2	5		10	20	50			
微小载重用	杆部直角方向载荷 LVSA-A 																							2-59
	杆部水平方向载荷 LTS-A 																							2-59
高精度伸缩式	精度1/3333 LTZA-A 																							2-44
伸缩式	高温用、低温用 LTF(H·L) 																							2-26

拉伸压缩两用测量用		额定容量														登载页								
		N				kN								MN										
		50	100	200	500	1	2	5	10	20	50	100	200	500	1		1.5	2						
低容量拉伸 压缩两用	低容量 LUA-A 																							2-56
拉伸压缩两 用小型	直径28mm, 重量80g LURA-SA1 																							2-51
	小型 LUXB-ID 																							2-52
拉伸压缩 两用	惰性气体封闭 LUE 																							2-47
高精度拉伸 压缩两用	精度1/5000 LUHF 																							2-57
拉伸压缩 两用	薄型, 高容量 LUKA-A 																							2-49

拉伸压缩两用载荷传感器的伸缩为(+)输出, 压缩为(-)输出。



## 载荷传感器选择表



分力传感器			额定容量								登载页			
			N						kN					
			10	20	50	100	200	300	500	1		3		
型号名称														
3分力传感器	3分力测量用 LSM-B-SA1		●	●	●	●	●			●			2-66	
6分力传感器	6分力测量 LAT-1000A									●			2-64	
小型6分力传感器	6分力测量 LFM-A											●	●	2-62
带放大器小型6分力传感器	6分力测量 LFX-A											●	●	2-63

特殊型 钢铁生产线用载荷传感器			额定容量								登载页				
			kN					MN							
			5	10	20	30	50	100	1	2		3	5		
型号名称															
张紧仪器用	张紧仪器用 LCR-B-S7		●	●	●	●	●	●						2-72	
垫圈式	垫圈式, 压延机用 LCW-D-S										●	●	●	●	2-43
	垫圈式, 压延机用 LCW-E-S										●	●	●	●	2-43

特殊型			额定容量									登载页			
			kN						MN						
			10	20	30	50	100	200	300	500	1		1.5	2	
型号名称															
垫圈式	适合相同容量不同直径的機種 LCW-C-SA3		●	●		●	●	●	●						2-42
销形	用于滑轮轴 LTP-S-S		●	●		●	●	●		●					2-70
千斤顶用	千斤顶用 LUR-B-SA1		●	●	●	●	●	●	●	●	●	●	●	●	2-67
伸缩式单侧旋转	绳缆张力测量用 LTR-S-SA1			●	●	●									2-69
起重机	LTA-C-S			●		●	●	●	●	●					2-68
方形	轴台载荷用 LCD-A-S				●	●	●								2-71